	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition
1	BRS	L1	16172	configuration near5 optim\$5	US- PGPUB; USPAT	2005/01/21 22:37		
2	BRS	Ĺ2	4212	test\$3 same configuration same performance	US- PGPUB; USPAT	2005/01/21 22:38		
3	BRS	L3	3581	analyz\$3 near5 configuration	US- PGPUB; USPAT	2005/01/21 22:38		
4	BRS	L4	610	1 and (2 or 3)	US- PGPUB; USPAT	2005/01/21 22:40		
5	BRS	L5	5882	bus same card same slot	US- PGPUB; USPAT	2005/01/21 22:40		
6	BRS	L6	4676	pci near5 card	US- PGPUB; USPAT	2005/01/21 22:41		
7	BRS	L7	4165	pci near5 slot	US- PGPUB; USPAT	2005/01/21 22:41		
8	BRS	L8	1354	5 and 6 and 7	US- PGPUB; USPAT	2005/01/21 22:41		τ
9	BRS	L9	3	4 and 8	US- PGPUB; USPAT	2005/01/21 22:46		
10	BRS	L10	46044	transfer near3 rate	US- PGPUB; USPAT	2005/01/21 22:47		
11	BRS	L11	16	4 and 10	US- PGPUB; USPAT	2005/01/21 22:59		
12	BRS	L12	270	8 and 10	US- PGPUB; USPAT	2005/01/21 22:59	·	
13	BRS	L13	2831	713/1.ccls. 713/2.ccls. 713/100.ccls.	US- PGPUB; USPAT	2005/01/21 23:00		
14	BRS	L14	749	710/104.ccls.	US- PGPUB; USPAT	2005/01/21 23:00		
15	BRS	L15	3414	13 or 14	US- PGPUB; USPAT	2005/01/21 23:00		

	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition
16	BRS	L16	15	12 and 15	IPGPUB:	2005/01/21 23:00		